

Park Inspections issues & other ongoing issues

GLEBE

Bike Humps

Bike humps need attention. Lots of holes and debris within the surface. All surrounding fencing has rotted and some is missing.

Update: 11/11/21 – Councillor suggested adding to the Council Strategy.

Wellhouse Park

Surface (repairs coming loose, shrinkage).

Update: obtain quotes to resurface entire park for 2023/24 budget.

Glebe 1

Remove compost pile from behind cricket nets (grass/weeds/dead flowers from tennis club and cricket club square).

Update: to obtain quotes.

WEST MERSEA PARK

School Gardens

Concrete bridge.

Path parallel to Barfield Road.

Bandstand surrounding paving and path leading into bandstand.

Play surface under swings (vandalised and not at correct depth for safety).

Stump removal.

Update:

Quote received for removal of parallel path, removal of bandstand paths. Relaying path leading into bandstand (to comply with disability access).

Obtaining quotes for resurfacing.

To obtain quote for stump removal (including cemetery and churchyard).

Youth Field

French drain.

Surfacing under single point swing.

Hawthorn hedge to near basket swing.

Bin to near basket swing.

Update:

Quote obtained for installation of French drain.

Obtaining quotes for surfacing under swing.

Hawthorn hedge has a TPO and permission was not granted to cut it back so therefore its overgrown. Advise sought from RoSPA re spiky hedge, suggested removal as too close to play equipment.

Skatepark

Loose grind rail.

Exposed corners on skatepark bowl.

Main entrance

Ditch needs to be cleared out.

Reymead Wood and Open Space

Local resident has left paving slabs adjacent to their new fence.

Gate rotten.

Chip log pile.

Update: sent a letter informing the resident to remove the slabs.

Obtain quote for new gate – add to 2023/24 budget.

Quote obtained to chip log pile.